

Includes everything needed for O₂ Safe Shock & Stain Solution #2 treatment:

- (3) 2 lb. O₂Safe Shock™
- (1) 10 lb. The Copper & Scale Stuff™
- (2) 32 oz. The Purple Stuff[®]
- (1) 9 oz. The Filter Fiber Stuff™











"Get with The Program!"





REMOVAL





Stain Solution #3 (O2 Safe Shock™) & Stain Solution #2 Treatment (The Copper & Scale Stuff ™)

Treatment Prerequisites DO NOT PROCEED IF THE FOLLOWING CONDITIONS HAVE NOT BEEN MET CONTACT JACK'S MAGIC TECHNICAL SUPPORT FOR ASSISTANCE

- Positive reaction for this treatment with Jack's Magic Stain ID Kit
- Water Temperature must be above 65°F
- Isolate all heaters and/or heat pumps from circulation system
- Isolate or remove ionizers, mineral systems and chemical feeders; turn off salt generators
- This treatment is recommended for pools up to 35,000 gallons; contact a Jack's Magic technician for larger pools
- Properly balanced water for stain treatment (see chart below)

TIP: Do not swim during this treatment. If you cannot close the pool for the duration of a Stain Solution #3 and #2 Treatment (48 hours – 2 weeks), contact a Jack's Magic representative for an alternative solution.

1. Balance pool water to the following parameters:

BALANCE PARAMETERS for STAIN IDENTIFICATION AND REMOVAL	
Pool Water Item:	Balance Parameter(s)
Free and Total Available Chlorine (FAC & TAC)	1-3 ppm
рН	7.0-7.4
Total Alkalinity (TA)	80 ppm or below
Calcium Hardness (CH)	200 - 400 ppm
Cyanuric Acid (Stabilizer) (CYA)	Below 70 ppm
Total Dissolved Solids (TDS)	Below 1,200 ppm (4,000 ppm in salt systems)

- 2. Turn pool pump on.
- 3. Add ½ gallon Muriatic (pool) Acid per 10,000 gallons of pool water <u>AFTER</u> the pH and TA are adjusted.
- 4. Add Jack's Magic® the Blue Stuff® at a rate of 1 quart per 10,000 gallons of pool water.

TIP: With salt (chlorine generator) system or high TDS (over 1,200 ppm) substitute **the Purple Stuff**® in place of **the Blue Stuff**.

- 5. Add **STAIN SOLUTION #3 O2 Safe Shock** at a rate of 5 pounds per 10,000 gallons. Wait 15-20 minutes.
- 6. Add 10 pounds of Jack's Magic **STAIN SOLUTION #2 the Copper & Scale Stuff** per 10,000 gallons of pool water. Pre-dilute product or brush any undissolved product immediately as it reaches the bottom.
- 7. Circulate pool continuously on high speed for the duration of the treatment (48 hours 2 weeks).

TIP: Use the Filter Fiber Stuff™ to enhance filtration in a sand or cartridge system for a more efficient removal.